UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office

ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS P.O. Box 1450

Alexandria, VA 22313-1450

September 9, 2006

ECKERT SEAMANS CHERIN & MELLOTT 600 GRANT STREET 44TH FLOOR

PITTSBURGH PA 15219

Patent No. : 7,048,779 B1

Inventor(s)

: Thomas Weyand, et al.

Issued

: May 23, 2006

For

METHOD OF REMOVING MERCURY

FROM EXHAUST GASES OF COAL FIRED

POWER PLANTS AND ASSOCIATED

APPARATUS

Doc. No. 164319-00027

To Whom It May Concern:

The Certificate of Correction issued on <u>August 29, 2006</u>, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The application number in the heading of cofc has been incorrectly entered on issued cofc by the PTO. A superseding cofc will be issued to correct the application number to read as -- 09/720,589--.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 308-9390 ext. 111 For Cecelia Newman, Supervisor Decisions & Certificates of Correction Branch (703) 305-8309 / 703-308-9390 ext. 102 cbn